

# THE CHIEF INSPECTOR OF BOILERS, WEST BENGAL

New Secretariat Buildings ( 8th floor )

1, K. S. Roy Road,

CALCUTTA-1

SIR,

Name of owners— M/s. Techno Engineering,

Locality— Hirapur, Deriachak, Purba Medinipur, Pin : 721 151

Boiler No.— // Type— // Date of Inspection— 27.11.2002

Sub : Inspection of the establishment of the applicant at their workshop

Ref : ~~Application~~ Applicant's letter CD/PD/NJ/KTP/02/302 dtd. 19.11.2002.

.....

With reference to above and as per the direction of Chief Inspector of Boilers, W.B. I paid a visit to the above noted premises and my observations are as follows : -

- a) Technical personnels of the organisation like owners, Engineers, Supervisors, Welders, Fitters etc. were met and their experiences in the respective fields appeared to be suitable for taking up jobs ~~including~~ involving erection of boilers and pipelines and overhauling and repairs of utility water tube boilers.
- b) Equipments and Tools & Tackles etc. like Welding Generators, Grinding Machines, Drill Machines, cutting sets, Pipe bending machines, Chain Pulley Blocks, Portable Ovens, D'shakles, Wire ropes etc. were verified and found to be in order. During inspection, it was pointed out by the owner of the organisation that all the tools and tackles could not be presented due to the fact that some of the equipment were sent to their work-sites.
- c) From the list of jobs executed by the organisation and other credentials attached to the application, it appears that the company had carried out many repairing jobs as sub-contractor including mostly utility 200 MW water tube boilers. The Company have also experience in erection of water tube boilers and pipe line as sub-contractor.
- d) From the discussions, I had with the concerned personnels of the Company, it was known that outside agency approved by this Directorate will be employed to carry out necessary N.D.T., and heat treatment of weld joints which will be done at site.

In view of above, it is recommended that the organisation may be accorded permission provisionally for a period of one year from the date of issue of this report to carry out the following jobs coming under the purview of IBB.

- 1) Erection of boilers upto a maximum capacity 100 Tons/Hr.
- 2) Fabrication and Erection of Class I Steam and Feed Water Piping.
- 3) Repairing of Water Tube boilers upto a maximum steaming capacity of 700 Tons/Hr.

Chief Inspector of Boilers, West Bengal, Form No. 21  
ACJP—A 77—1995-96—20,000

Yours faithfully,

  
Dy. Chief Inspector of Boilers, W.B.

- P. T. O. -  
26/12/2002

No. P/3002 dt. 26-12-02

~~Copy to be sent~~

Copy forwarded for information and necessary to M/s. Techno Engineering, Hirapur, Deriachak, Purba Medinipur, Pin : 721 151. They are accorded approval provisionally for one year for the purpose mentioned above in the last para from the date of issue of this letter.

*Agul* 26.12.02  
Chief Inspector of Boilers, W.B.

CHIEF INSPECTOR OF BOILERS  
GOVT. OF WEST BENGAL

d231202.

*En*  
23/12

*[Faint, mostly illegible text, likely bleed-through from the reverse side of the page]*

# THE CHIEF INSPECTOR OF BOILERS, WEST BENGAL

New Secretariat Buildings ( 8th floor )

1, K. S. Roy Road,

KOLKATA-700 001

SIR,

Name of ~~owner~~ Erector/Repairer : M/s. Techno Engineering.

Locality— Hiranpur, Deriachak, Purba Midnapur, Pin - 721 151.

Boiler No.— / Type— / Date of Inspection— /

Sub : Permission to act as Erector/Repairer under Directorate of Boilers.

Ref : 1) Provisional permission No. R/3002 dt. 26.12.2002.


2) Applicant letter for renewal No. CD/PD/HJ/GIB/03-04/23 dt. 14.2.2004.

With reference to the appeal put forward by the Erector/Repairer, this is to state that a permission may be granted for a period of one year from the date of issue of this letter provisionally to carry out erection/repair work of boilers as indicated in this office letter No. R/3002 dt. 26.12.2002.


An evaluation of the performance of the erector/repairer may be made after period of one year for continuance of the approval beyond one year.

Yours faithfully,

NO. R/544 DT. 27/2/04

  
27/2/2004  
Dy. Chief Inspector of Boilers, W.B.

✓ Copy forwarded for information and necessary action to M/s. Techno Engineering,  
Hiranpur, Deriachak, Purba Midnapur, Pin - 721 151.

  
27/2/2004  
Chief Inspector of Boilers, West Bengal.  
CHIEF INSPECTOR OF BOILERS  
WEST BENGAL

